

Current needs for repairs and restoration

Work Scheduled for 2008 - 2009

**DMH Enterprises, Architects
104 Federal Street
Salem, MA 01970
617-745-2172**







Figure E-3. Orchard House, First Floor Plan, 1980, drawing by F.C. Detwiler, Architectural Historian.
DWT 9/81



Location of needed repairs and restoration of finishes


First Floor



 Indicates work scheduled for 2008


Location of needed repairs and restoration of finishes

First Floor



Location of needed repairs and restoration of finishes

Second Floor



 Indicates work scheduled for 2008

Location of needed repairs and restoration of finishes

Second Floor

Note deflection of window

Repair wall structure

105 Repair wall structure 203 Repair wall structure

Repair porch structure

103 Repair entrance



Location of needed repairs and restoration of finishes

DSCN7986

South facade



Repair wall structure

106 Repair wall structure

205 Repair wall structure

DSCN6516

107 Repair wall structure

206 Repair wall structure

Repair wall structure (interior)

Location of needed repairs and restoration of finishes

Wall opened up previously to view conditions



DSCN6515

West facade

Structure inside south and west walls needs repairs



DSCN2224



DSCN2227

Views of Alcott's Study

Structure inside east wall needs repairs



DSCN2232

DSCN2233

Views of parlor



“Temporary” post to be removed and ceiling structure reinforced

Plaster repairs needed

DSCN2237

Views of Kitchen



DSCN2238



Kitchen3

Views of Kitchen

This photo is “before” restoration and needs are to carefully reconstruct the drying rack and cabinetry

This photo is “during” restoration and needs are to repair plaster



KitchenDryingRack

Repair structural system



DSCN2240

Views of dining room



DSCN2239




Structure inside partition needs repairs



DSCN2252

Views of Louisa May's Room

DSCN9133



Second Floor



DSCN2256

Structure needs repair, steel column removed and finishes restored



DSCN2257