
South Union School Southborough, MA Building Elevations and Plans 2008 Work


11/13/2008, Revised 1/9/2009 (Floor Plans colored windows pages 3-5, Elevations colored windows pages 7-10, Window Door Schedule clarified pages 12-15, Window Details added pages 18, 19)


DMH Enterprises, Architects 104 Federal Street Salem, MA 01970 617-745-2172 davidatsalem@comcast.net The following pages detail the window and door numbering system and describes the type of storm window to be installed.

"Op w/Scn" is operable with screen. All others are fixed panels, although they can be removed and reinstalled at will.

Some windows (such as the boarded up basement windows) are not scheduled to be treated.







The following pages detail the treatment for each window and describe the type of storm window to be installed.

```
1= Base Bid
2 = Add Alternate 1
3 = Add Alternate 2
4 = Add Alternate 3
```

A colored number indicates 2008 work. All others are scheduled for 2009 or later, depending upon the monies available and the bidding results.



West Approach Stair

South Elevation



East Elevation



North Elevation



vvesi Lievaliuli

The following pages describe the characteristics of each window and door and detail the treatment for each window and describe the type of storm window to be installed.

0 = Base Bid

1 = Add Alternate 1

2 = Add Alternate 2

3 = Add Alternate 3


seria	Win		/Door/S	Stair Work	Size Type Fixed	Size Type DH	Storm Type Fixed	Storm Type Operable	Storm Type Screen	Grate	Blocked	Notes	Repair Hardware	Phase
2	002	South	Basement	3'0 X 3'5	X					X			Remove grate, prepare and repaint. Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, reinstall sash, reinstall grate.	0
3	003	South	Basement	3'0 X 3'5	X					Х			Remove grate, prepare and repaint. Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, reinstall grate.	0
4	004	South	Basement	3'0 X 3'5	X					X			Remove grate, prepare and repaint. Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, reinstall sash, reinstall grate.	0
8	103	South	First	2'9 X 7'0		X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall automatically locking sash. Install interior storm window Install two lift handles or lower sash, install automatically locking device.	0
9	104	South	First	2'9 X 7'0		X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	0
25	105	South	First	2'9 X 7'0		X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	0
26	106	South	First	2'9 X 7'0		X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window Install two lift handles or lower sash, install automatically locking device.	n 0
29	109	East	First	4'0 X 7'6		X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sattomatically locking sash. Install interior storm window Install two lift handles or lower sash, install automatically locking device.	0
42	110	East	First	4'0 X 7'6		X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	0


Page 1

10	Win		w/Door/	Stair Work	Size Type Fixed	Size Type DH	Storm Type Fixed	Storm Type Operable	Storm Type Screen	Grate	Blocked	Notes	Repair Hardware	Phase
serial	No	1 11 <u>12</u> - 55	12 1470 SEC		55		S			9	B	Notes	Table 1 4575 - March Dermark 1 1755 arms 500000 Section 60000	
43	111	East	First	4'0 X 7'6		X		Х	Х				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window Install two lift handles lower sash, install automatically locking device.	on 0
44	112	East	First	4'0 X 7'6		X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window Install two lift handles lower sash, install automatically locking device.	on 0
45	113	East	First	4'0 X 7'6		X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	0
55	114	North	n First	4'0 X 7'6		X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sattomatically locking sash. Install interior storm window Install two lift handles lower sash, install automatically locking device.	on 0
56	115	North	n First	4'0 X 7'6		X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	0
57	116	North	n First	4'0 X 7'6		X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	0
58	117	North	n First	4'0 X 7'6		X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall automatically locking sash. Install interior storm window Install two lift handles lower sash, install automatically locking device.	on 0
59	118	West	First	4'0 X 7'6		X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	0
66	119	West	First	4'0 X 7'6		X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall automatically locking sash. Install interior storm window Install two lift handles lower sash, install automatically locking device.	on 0

serial	Wind		/Door/S	Stair Work Size	Size Type Fixed	Size Type DH	Storm Type Fixed	Storm Type Operable	Storm Type Screen	Grate	Blocked	Notes	Repair	Hardware	Phase
67	120	West	First	4'0 X 7'6		Х	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window		0
68	121	West	First	4'0 X 7'6		X		X	Х				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	Install two lift handles on lower sash, install automatically locking device.	0
69	122	West	First	4'0 X 7'6		X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window		0
														Total Base/Alternate 0	
70	D1	South	First	2'9 X 6'11									Remove dead bolts and fill, repair base with Abatron epoxy fillers, sand smooth, repaint	Install new set Von Duprin 98/9975 Mortise Lock Exit Device with new exterior lock set.	1
71	D2	South	First	2'9 X 6'11									Repair base with Abatron epoxy fillers, sand smooth, repaint	Install new set Von Duprin 98/9927 Series Exit Device (Vertical Bar).	1
72	D3	South	First	2'9 X 6'11								Exterior Door, East Set, LH (from exterior)	Remove dead bolts and fill, repair base with Abatron epoxy fillers, sand smooth, repaint	Install new set Von Duprin 98/9975 Mortise Lock Exit Device with new exterior lock set.	1
73	D4	South	First	2'9 X 6'11								Exterior Door, East Set, RH (from exterior)	Repair base with Abatron epoxy fillers, sand smooth, repaint	Install new set Von Duprin 98/9927 Series Exit Device (Vertical Bar).	1
														Total Base/Alternate 1	


serial	Wind			tair Work	Size Type Fixed Size Type DH	Storm Type Fixed	Storm Type Operable	Storm Type Screen	Grate	Blocked	Notes	Repair	Hardware	Phase
76											West approach stair. Repair concrete	Excavate cracks and repair cracks horizontal and vertical with Abatron Aboweld 55-1 epoxy filler. Hold back final surface 1/16 inch and sprinkle sand on wet joint to match adjoining surface.		2
77											West door stair. Repair concrete	Excavate cracks and repair cracks horizontal and vertical with Abatron Aboweld 55-1 epoxy filler. Hold back final surface 1/16 inch and sprinkle sand on wet joint to match adjoining surface.		2
78											East door stair. Repair concrete	Excavate cracks and repair cracks horizontal and vertical with Abatron Aboweld 55-1 epoxy filler. Hold back final surface 1/16 inch and sprinkle sand on wet joint to match adjoining surface.		2
													Total Base/Alternate 2	
60	222	West	Second	4'0 X 8'0	X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	Install two lift handles on lower sash,	3
61	223	West	Second	4'0 X 8'0	X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window		3
62	224	West	Second	4'0 X 8'0	X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window		3
63	225	West	Second	4'0 X 8'0	X	X						Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window		3
64	226	West	Second	4'0 X 8'0	X		X	X				Remove sash, remove loose glazing, replace missing glazing with new compound, prime paint, repaint sash, re-rope sash, reinstall sash. Install interior storm window	Install two lift handles on lower sash,	3
													Total Base/Alternate 3	
													Page 4	







L1080874 L1080872

East Door West Door 16




Section at Jamb






Typical Window Interior





Typical Window Interior View, Operable Storm Window Location Only




Typical Window Interior View, All Other Windows








Allied Window Fixed Unit



Allied Window Operable Unit




Repair all cracks in treads and risers with Abatron Aboweld 55-1


L1080453



Repair tread with Abatron Aboweld 55-1

Approach stair to be repaired





East stair to be repaired