

**First Congregational Church  
Nantucket, MA  
Interior Repairs, Restoration and Conservation**

**September 12, 2007**

**DMH Enterprises, Architects  
104 Federal Street  
Salem, MA 01970  
617-745-2172**

**Donald Mroz, Ph.D.  
Waves of Change Partnership  
268 Madaket Rd,  
Nantucket, MA 02554  
508-228-5398**

**Trompe l'oeil to be repainted, ceiling and walls**


**Appropriate handrails to be added to pulpit area**



L1030232

**Sanctuary, looking west**


Interior Wall  
Mold and  
discolored




Front  
Inside  
Church



Interior Cracks and Peeling



**Detail of walls and  
decorative trompe l'oeil  
to be repainted**



**Detail of walls and  
wooden paneling to be  
repainted**

First Congregational Summer Church  
Interior Pictures  
(Ceiling)




Ceiling behind  
Organ in Summer  
Church



Ceiling cracked and peeling

Window behind Organ facing  
Center Street



**Detail of sanctuary  
plaster rosette and ceiling  
plaster behind organ to  
be repaired.**

**Interior of windows to be repaired and repainted**



L1030184

**Sanctuary, looking west**

DSCN0570

**Detail of window sash and frame deterioration at interior of sanctuary to be repaired and repainted.**



DSCN0574



DSCN0572



DSCN0573

**Narthex plaster wall and ceilings to be repaired and repainted**



**Narthex, looking east**



L1050475



L1030220

**Two exterior side doors to be repaired and panic hardware installed**

**Exterior, south and north facades**



L1030233

**Proper lighting to be installed in stair  
areas of tower where public has access**

**Tower interior, typical**