


**Current needs for repairs and restoration**

**Future Work to be done**

**April 17, 2009**




 Indicates work scheduled for 2008


Location of needed repairs and restoration of finishes



Indicates work scheduled for 2009

First Floor



 Indicates work scheduled for 2008

Location of needed repairs and restoration of finishes



Indicates work scheduled for 2009

Second Floor



**Repair porch structure**

**103 Repair entrance**

**Location of needed repairs and restoration of finishes**

**DSCN7986**

**South facade**



“Temporary” post to be removed and ceiling structure reinforced

Plaster repairs needed

DSCN2237

Views of Kitchen



DSCN2238



This photo is "before" restoration and needs are to carefully reconstruct the drying rack and cabinetry

This photo is "during" restoration and needs are to repair plaster



**Kitchen3**

**KitchenDryingRack**

Views of Kitchen