

First Congregational Church

Nantucket, MA

© David M. Hart AIA 2006

List View by Base/Alternate

61

Record	Item No.	Building	Level	Item/Type	Group	Base	Alt1	Alt2	Alt3	Alt4	Alt5	Alt6	Alt7
107	501	1834 Church		Drive all steel nails in and putty holes	Base/Alternate	X	a						
27	E 1	1834 Church	East	Spire Spire plywood repairs	Base/Alternate	X	a						
67	E 2	1834 Church	East	Spire Spire plywood repairs	Base/Alternate	X	a						
19	E 3	1834 Church	East	Louv Consolidate sill	Base/Alternate	X	a						
23	E 4	1834 Church	East	Louv Louver Level East Louver Repairs	Base/Alternate	X	a						
68	E 5	1834 Church	East	Louv Replace rotted area	Base/Alternate	X	a						
69	E 6	1834 Church	East	Louv Caulk dutchmen	Base/Alternate	X	a						
70	E 7	1834 Church	East	Obse Consolidate sill	Base/Alternate	X	a						
71	E 8	1834 Church	East	Obse Consolidate sill	Base/Alternate	X	a						
5	E 9	1834 Church	East	Obse Louver repairs	Base/Alternate	X	a						
72	E 10	1834 Church	East	Louv Consolidate decorative detail	Base/Alternate	X	a						
73	E 11	1834 Church	East	Obse Replace rotted area	Base/Alternate	X	a						
76	E 30	1834 Church	East	Paint East facade upper tower	Base/Alternate	X	a						
78	N 101	1834 Church	North	Spire Gild Weathervane	Base/Alternate	X	a						
79	N 102	1834 Church	North	Spire Examine lightning protection, make repairs	Base/Alternate	X	a						
24	N 103	1834 Church	North	Louv Louver Level North Louver Repairs	Base/Alternate	X	a						
80	N 104	1834 Church	North	Obse Consolidate sill	Base/Alternate	X	a						
81	N 105	1834 Church	North	Obse Consolidate sill	Base/Alternate	X	a						
82	N 106	1834 Church	North	Obse Consolidate sill	Base/Alternate	X	a						
9	N 107	1834 Church	North	Obse Lower arched window shutter repairs north	Base/Alternate	X	a						
16	N 108	1834 Church	North	Obse Bell Level North Repairs replace rot	Base/Alternate	X	a						

Record	Item No.	Building	Level	Item/Type	Group	Base	Alt1	Alt2	Alt3	Alt4	Alt5	Alt6	Alt7
83	N 109	1834 Church	North	Louv	Caulk dutchmen	Base/Alternate	X						
50	N 114	1834 Church	North		Paint North facade upper	Base/Alternate	X						
94	S 301	1834 Church	South	Obse	Replace rotted area	Base/Alternate	X						
53	S 302	1834 Church	South	Spire	Spire plywood repairs	Base/Alternate	X						
95	S 303	1834 Church	South	Spire	Spire plywood repairs	Base/Alternate	X						
96	S 304	1834 Church	South	Spire	Spire plywood repairs	Base/Alternate	X						
97	S 305	1834 Church	South	Spire	Spire plywood repairs	Base/Alternate	X						
22	S 306	1834 Church	South	Louv	Replace all trim	Base/Alternate	X						
98	S 307	1834 Church	West	Obse	Consolidate sill	Base/Alternate	X						
99	S 308	1834 Church	West	Obse	Consolidate sill	Base/Alternate	X						
100	S 309	1834 Church	West	Obse	Consolidate sill	Base/Alternate	X						
101	S 310	1834 Church	East	Louv	Consolidate decorative detail	Base/Alternate	X						
25	S 311	1834 Church	South	Louv	Louver Level West Louver Repairs	Base/Alternate	X						
110	S 312	1834 Church	South	Obse	Lower arched window shutter repairs south	Base/Alternate	X						
51	S 317	1834 Church	South		Paint South facade upper	Base/Alternate	X						
87	W 201	1834 Church	West	Obse	Replace rotted area	Base/Alternate	X						
21	W 202	1834 Church	West	Louv	Louver Level West Repairs	Base/Alternate	X						
88	W 203	1834 Church	West	Obse	Consolidate sill	Base/Alternate	X						
89	W 204	1834 Church	West	Obse	Consolidate sill	Base/Alternate	X						
90	W 205	1834 Church	West	Obse	Consolidate sill	Base/Alternate	X						
13	W 206	1834 Church	West	Obse	Bell Level West Louver Repairs	Base/Alternate	X						
91	W 207	1834 Church	West	Louv	Consolidate decorative detail	Base/Alternate	X						
31	W 210	1834 Church	West		Paint West facade upper	Base/Alternate	X						
114	W 212	1834 Church	West	Louv	Caulk dutchmen	Base/Alternate	X						

Record	Item No.	Building	Level	Item/Type	Group	Base	Alt1	Alt2	Alt3	Alt4	Alt5	Alt6	Alt7
36	E	13 1834 Church	East	Towe Arched window, replace trim	Base/Alternate	alt1							X
55	E	14 1834 Church	East	Base Pilaster left, replace	Base/Alternate	alt1							X
56	E	22 1834 Church	East	Base Pilaster right, replace	Base/Alternate	alt1							X
111	E	33 1834 Church	East	Towe Replace all soffit and fascia	Base/Alternate	alt1							X
<hr/>													
84	N	110 1834 Church	North	Base Pilaster left, replace	Base/Alternate	alt1							X
85	N	111 1834 Church	North	Base Pilaster right, replace	Base/Alternate	alt1							X
<hr/>													
103	S	313 1834 Church	South	Base Pilaster right, replace	Base/Alternate	alt1							X
102	S	314 1834 Church	South	Base Pilaster left, replace	Base/Alternate	alt1							X
<hr/>													
93	W	208 1834 Church	West	Base Pilaster left, replace	Base/Alternate	alt1							X
92	W	209 1834 Church	West	Base Pilaster right, replace	Base/Alternate	alt1							X
<hr/>													
<hr/>													
2	E	15 1834 Church	East	East Front door surround	Base/Alternate	alt2							X
58	E	16 1834 Church	East	Base Pilaster left, #2 south , replace	Base/Alternate	alt2							X
63	E	17 1834 Church	East	Base Blind Arch left, south , replace trim	Base/Alternate	alt2							X
57	E	18 1834 Church	East	Base Pilaster left, #1 south , replace	Base/Alternate	alt2							X
61	E	19 1834 Church	East	Base Blind Arch left, south , repair shutters	Base/Alternate	alt2							X
54	E	20 1834 Church	East	Base Replace water table and trim at base	Base/Alternate	alt2							X
4	E	21 1834 Church	East	Base Front door overlight, reglaze	Base/Alternate	alt2							X
59	E	23 1834 Church	East	Base Pilaster right, #1 north , replace	Base/Alternate	alt2							X
64	E	24 1834 Church	East	Base Blind Arch right, north , replace trim	Base/Alternate	alt2							X
60	E	25 1834 Church	East	Base Pilaster right, #2 north , replace	Base/Alternate	alt2							X
62	E	26 1834 Church	East	Base Blind Arch right, north , repair shutters	Base/Alternate	alt2							X
74	E	27 1834 Church	East	Base Replace clapboards	Base/Alternate	alt2							X

Record	Item No.	Building	Level	Item/Type	Group	Base	Alt1	Alt2	Alt3	Alt4	Alt5	Alt6	Alt7
75	E 28	1834 Church	East	Base	Replace clapboards	Base/Alternate	alt2	X					
1	E 31	1834 Church	East	Base	Front doors	Base/Alternate	alt2	X					
3	E 34	1834 Church	East	Base	Front door surround pilasters	Base/Alternate	alt2	X					
7	N 112	1834 Church	North	Base	Right side north facade replace trim on door	Base/Alternate	alt2	X					
77	N 113	1834 Church	North	Base	Replace water table and trim at base	Base/Alternate	alt2	X					
104	S 315	1834 Church	South	Base	replace trim on door surround repairs	Base/Alternate	alt2	X					
105	S 316	1834 Church	South	Base	Replace water table and trim at base	Base/Alternate	alt2	X					
28	E 29	1834 Church	East		Paint East facade lower	Base/Alternate	alt3		X				
29	N 115	1834 Church	North		Paint North facade lower	Base/Alternate	alt3		X				
30	S 318	1834 Church	South		Paint South facade lower	Base/Alternate	alt3		X				
106	W 211	1834 Church	West		Paint West facade lower	Base/Alternate	alt3		X				
10	E 12	1834 Church	East	Towe	Arched window, reglaze	Base/Alternate	alt4			X			
109	E 32	1834 Church	East	Base	Repair shutters located in Emerson basement,	Base/Alternate	alt4			X			
113	701	1834 Church	East		Restore spire with new copper roofing, paint	Base/Alternate	alt5				X		

Record	Item No.	Building	Level	Item/Type	Group	Base	Alt1	Alt2	Alt3	Alt4	Alt5	Alt6	Alt7
--------	----------	----------	-------	-----------	-------	------	------	------	------	------	------	------	------



108	505	1834 Church	East	Obse	Replicate (4) finials, install at upper deck, restore deck	Base/Alternate	alt6						X
-----	-----	-------------	------	------	--	----------------	------	--	--	--	--	--	---



112	506	1834 Church	East	Obse	Replicate (4) finials, install at lower deck, restore deck	Base/Alternate	alt7						X
-----	-----	-------------	------	------	--	----------------	------	--	--	--	--	--	---

