

Temperature/Humidity Levels

FCC Nantucket

serial	Project Number	Project	Date Reading	Time Reading	Instrument	Instrument Two	Location	Level	Building	Room	Item	Moisture Level	Inside		Outside		Notes	
													Temperature	RH Humidity	Temperature Outside	Humidity Outside		
211	3085	FCC Nantucket	8/12/2011	9:00	BK 725	Protimeter	Outside	East facade								74	56	
212	3085	FCC Nantucket	8/12/2011	9:00	BK 725	Protimeter	Inside	Museum Room		Museum Room	Plaster	6	80	60	74	56		
213	3085	FCC Nantucket	8/12/2011	9:15	BK 725	Protimeter	Inside	Bell Level			Plaster	20 - 22	80	55	74	56	North interior wall	
214	3085	FCC Nantucket	8/12/2011	9:15	BK 725	Protimeter	Inside	Bell Level			Plaster	17	80	55	74	56	West interior wall	
215	3085	FCC Nantucket	8/12/2011	9:15	BK 725	Protimeter	Inside	Bell Level			Plaster	14 - 15	80	55	74	56	South interior wall	
216	3085	FCC Nantucket	8/12/2011	9:30	BK 725	Protimeter	Inside	Observation Level			Plaster	9 - 14	76	55	74	56	South interior wall	
217	3085	FCC Nantucket	8/12/2011	9:30	BK 725	Protimeter	Inside	Observation Level			Plaster	12 - 14	76	55	74	56	North interior wall	
218	3085	FCC Nantucket	8/12/2011	9:30	BK 725	Protimeter	Inside	Observation Level			Plaster	13 - 19	76	55	74	56	West interior wall	
219	3085	FCC Nantucket	8/12/2011	9:30	BK 725	Protimeter	Inside	Observation Level			Plaster	11 - 16	76	55	74	56	East interior wall	
220	3085	FCC Nantucket	8/12/2011	9:30	BK 725	Protimeter	Outside	Observation Level			Wood	9 - 14, 32			74	56	North exterior wall, one spot on clapboard 32 moisture.	
221	3085	FCC Nantucket	8/12/2011	9:30	BK 725	Protimeter	Outside	Observation Level			Wood	12 - 15			74	56	East exterior wall	
222	3085	FCC Nantucket	8/12/2011	9:30	BK 725	Protimeter	Outside	Observation Level			Wood	21, 29, 25 - 32			74	56	West exterior wall	
223	3085	FCC Nantucket	8/12/2011	9:30	BK 725	Protimeter	Outside	Observation Level			Wood	25 - 32			74	56	South exterior wall	
224	3085	FCC Nantucket	8/12/2011	10:30	BK 725	Protimeter	Outside	Ground Level		South window sill	Wood	14 - 32			74	56	East exterior wall	
225	3085	FCC Nantucket	8/12/2011	10:30	BK 725	Protimeter	Outside	Ground Level		Clapboards, trim	Wood	6 - 8 - 14			74	56	East exterior wall	